

ANTENNA STRUCTURE (TOWER) LIGHT MALFUNCTION

DATE: 11/22/16

ISSUE: Beacon out on South Tower (ASR 1002064)

Reported to the FAA via the LEIDOS Outage Reporting Line.

REPORTED: November 11, 2016 (5:22pm)

Bruce Trogdon (B.T.) spoke with D.C.

NOTAM was issued for the tower which is valid for thirty (30) days.

NOTAM EXPIRES: December 22, 2016

NOTAM: HBI 11/005

12/21/16 extension until 1/22/17^{BT} 9pm

BT spoke with S.Y.

HBI 12/003

B.S. cancelled NOTAM on 1/5/17 8:17pm

BT spoke with BS

ANTENNA STRUCTURE (TOWER) LIGHT MALFUNCTION

DATE: 10/3/16

ISSUE: No lights on South Tower (ASR 1002064)

Reported to the FAA via the LEIDOS Outage Reporting Line at 7:28pm on Monday, October 3, 2016

Bruce Trogdon (B.T.) spoke with A.L. And a NOTAM was issued for the tower which is valid for fifteen (15) days.

REPORTED: October 3, 2016 (7:28pm)

NOTAM EXPIRES: October 18, 2016

Bruce Trogdon (B.T.) spoke with D.C. on October 17, 2016. A fifteen (15) day extension was granted until November 2, 2016.

NOTAM: HBI 10/015

NOTAM EXPIRES: November 2, 2016

Tower lights repaired on Monday, October 24.

Bruce Trogdon (B.T.) spoke with F.R. On Monday, October 24, 2016. NOTAM was cancelled.